




TRANSFORMERS

線性低頻電源變壓器
低頻焊線式-低電源變壓器

詳細產品規格--請點擊www.100y.com.tw

QuickConnectorLow-Volt.PowerTransformers



PartNo.	ProductNo.	Description	InputVolt.(ACV)	OutputVolt.(ACV)	Amp.(A)
27007	110-220V/0-12-0-12/2A	焊線式變壓器	110-220VAC	0-12-0-12VAC	2A
10508	110-220V/12-0-12V/0.5A	0.5A 焊線式變壓器	110V-220VAC	12V-0V-12VAC	0.5A
8357	110-220V/12-0-12V/1A	1 A 焊線式變壓器	110V/220VAC	12V-0V-12VAC	1A
27000	110-220V/20-0-20V	焊線式變壓器	110-220VAC	36V-0V-36VAC	
17514	110-220V/24-0-24V/1A	焊線式變壓器	110-220VAC	24V-0V-24V	1A
28051	110-220V/24V-0-24V/3A	焊線式變壓器	110-220VAC	24-0-24VAC	3A
8359	110-220V/3-0-3V/1A	1 A 焊線式變壓器	110V/220VAC	3V-0V-3VAC	1A
18434	110-220V/36-0-36V/2A	焊線式變壓器	110-220VAC	36V-0V-36VAC	2A
8355	110-220V/9-0-9V/0.5A	0.5A 焊線式變壓器	110V/220VAC	9V-0V-9VAC	0.5A
8356	110-220V/9-0-9V/1A	1 A 焊線式變壓器	110VAC/220VAC	9V-0V-9VAC	1A
15103	110V/10-0-10/2A	焊線式變壓器	110	10V-0-10V	2A
14387	110V/10-0-10V/3A	焊線式變壓器	0-110V	10-0-10V	3A
8268	110V/12-0-12V/0.25A	250mA 出線式變壓器	110VAC	12V-0V-12VAC	0.25A
5695	110V/12-0-12V/0.5A	0.5A 焊線式變壓器	0-110VAC	12-0-12VAC	0.5A
5697	110V/12-0-12V/1A	焊線式變壓器	0-110V	12-0-12Vac	1A
7666	110V/12-0-12V/2A	2 A 焊線式變壓器	0-110V	12V-0V-12VAC	2A
17832	110V/12-0-12V/3.5A	焊線式變壓器	110VAC	12V-0V-12VAC	3.5A
8271	110V/12-0-12V/3A	焊線式變壓器	110VAC	12V-0V-12VAC	3A
7997	110V/15-0-15/0.5A	焊線式變壓器	0V-110V	15-0-15Vac	0.5A
5696	110V/15-0-15V/1A	焊線式變壓器	0-110V	15-0-15Vac	1A
10577	110V/15-0-15V/2A	焊線式變壓器	110VAC	15V-0V-15V	2A
15952	110V/18V-0-18V/0.5A	焊線式變壓器	110VAC	18V-0V-18VAC	0.5A
16081	110V/18V-0-18V/3A	焊線式變壓器	110VAC	18V-0V-18VAC	3A
8269	110V/24-0-24V/0.25A	帶線式變壓器	110VAC	24V-0V-24VAC	0.25A
7996	110V/24-0-24V/0.5A	焊線式變壓器	0V-110V	24-0-24Vac	0.5A
10576	110V/24-0-24V/1A	焊線式變壓器	110VAC	24V-0V-24V	1A
12244	110V/24-0-24V/2A	焊線式變壓器	0-110VAC	24V-0V-24VAC	2A
8270	110V/24-0-24V/3A	焊線式變壓器	110VAC	24V-0V-24VAC	3A
17066	110V/24-0-24V/4A	焊線式變壓器	0-110VAC	24V-0V-24VAC	4A
5698	110V/28-0-28V/1A	焊線式變壓器	0-110VAC	28-0-28Vac	1A
14286	110V/28-0-28V/2A	焊線式變壓器	0-110VAC	28-0-28Vac	2A
14524	110V/3-4-6-9-12V/1A	焊線式變壓器	110-0	3-4-6-9-12-V	1A
14633	110V/3.3V/10A	帶線式變壓器	110V	3.3V	10A
12243	110V/36-0-36V/1A	焊線式變壓器	0-110VAC	36-0-36Vac	1A
8634	110V/36-0-36V/2A	焊線式變壓器	110VAC	36V-0V-36VAC	2A
8633	110V/36-0-36V/3A	焊線式變壓器	110VAC	36V-0V-36VAC	3A
10578	110V/40-0-40V/3A	焊線式變壓器	110VAC	40V-0V-40V	3A
4724	110V/6-0-6V/0.25A	帶線式變壓器	0-110Vac	6-0-6Vac	0.25A
4723	110V/6-0-6V/0.5A	焊線式變壓器	0-110VAC	6-0-6VAC	0.5A
7999	110V/6-0-6V/1A	焊線式變壓器	0V-110V	6-0-6VAC	1A
12245	110V/6-0-6V/2A	焊線式變壓器	0-110VAC	6-0-6Vac	2A
8358	110V/7.5-0-7.5V/1A	焊線式變壓器	110VAC	7.5V-0V-7.5VAC	1A
4725	110V/9-0-9V/0.25A	帶線式變壓器	0-110Vac	9-0-9Vac	0.25A
7998	110V/9-0-9V/0.5A	焊線式變壓器	0V-110V	9-0-9Vac	0.5A
9250	110V/9-0-9V/1A	焊線式變壓器	0-110VAC	9V-0V-9VAC	1A

