
M.M.M. 100 A.C. 勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-54151736 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw

WWW

WWW.100Y.C

WW.100Y.CO



Parts	Material	Plating (Micro-inch)
Ferrule	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Brass	Gold 20 Over Nickel 50 Over Copper 50
Renber Ring	Beryllium Copper	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	W. W. W. CO. W. I.W.
Insulator	Teflon	LIN WWW.IO. CO. T. T.
Body	Stainless	Passivated
Coupling Nut	Stainless	Passivated

Weight: 2.98 g

Suitable Cables: RG174, RG188, RG316, RG316-E, RG316-FEP

MMM.100X.COM; This part number complies with RoHS. TOTAL TOUR COM. TW

勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-54151736 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw

WWW.100Y.

## CABLE ASSEMBLY INSTRUCTION SMA3100S-0316 BODY **FERRULE CONTACT PIN** ASSEMBLY INSTRUCTION DIAGRAM 9.9 [.535] Step 1: STRIP AS SHOWN. 4.9 [.224] 2.5 [.098] В Step 2: SLIDE FERRULE "A" OVER CABLE. Step 3: PUT PIN "B" ON CENTER CONDUCTOR AND SOLDER IN "Y". C Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR "C" IN PLACE. Step 5: SLIDE FERRULE "A" TOWARDS THE CONNECTOR "C" AND CRIMP.

This part number complies with RoHS.