## W.100Y.COM.TW RPM TRANSMITT

Model: TR-RPM1A4 ISO-9001, CE, IEC1010



WW.100Y.COM.TW



勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-34970699 胜特力电子(深圳) 86-755-83298787 Http://www. 100y. com. tw

WWW.100Y.COM.TW





The Art of Measurement

## RPM TRANSMITTER

Model: TR-RPM1A4

Measure	Range 1 :	Range 2 :
Range	100-2,000RPM	1,000 RPM - 20,000 RPM
Output	4 - 20 mA	
	Range 1 :	Range 2 :
	100  RPM = 4.8  mA	1,000  RPM = 4.8  mA
	1,000  RPM = 12  mA	10,000  RPM = 12  mA
	2,000  RPM = 20  mA	20,000  RPM = 20  mA
External	ZERO VR	TW WWW.100X.COM.TW
Adjustment	SPAN VR	
Power	90 - 260 ACV	
Supply	50 Hz/60 Hz	
Operation	0 - 50 °C	
Temperature	32 - 122 °F	
Operation	Less than	
Humidity	80 %RH	OX.COM.TW WWW.100Y.CO
Accessory	RPM sensor is optional.	
Included	WW. TOOK COM.	100X.COM.TW WWW. 100X.
Optional	Proximity sensor: PX-01	100X.COM.TW WWW.100Y
Accessories	Photo sensor: PI-06	
Mounting	Din rail or Wall	
Case	ABS plastic	
Others	*3 wires connection	
	*Exciting voltage DC 12 V	

<sup>\*</sup> Appearance and specifications listed in this brochure are subject to change without notice.