2000A DCA/ACA CLAMP+DMM

Model: CM-9930 *ISO-9001, CE, IEC1010*







FEATURES

- * 2 in 1, 2000 A clamp meter + Digital multimeter.
- * Meet IEC 1010 CATIII 1000V safety requirement.
- * True rms reading for ACV & ACA measurement.
- * 4000 counts, Auto range,
 multi-functions for ACA, DCA,
 ACV, DCV, Ohms, Capacitance,
 Hz, Diode, Duty cycle and
 continuity check.
- * LSI circuit provides high reliability and durability.
- * Wide ranges (2000A, 400 A) clamp on current measurement both for ACA & DCA.
- * 4 ranges (400 uA, 4000 uA, 40 mA, 400 mA) direct current input measurement both for ACA & DCA.
- * Overload protection circuit is provided for all ranges.
- * Data hold, Relative key, Back light.

勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-34970699 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw

The Art of Measurement

2000A DCA /ACA CLAMP METER + DMM, 2 in 1 Model : CM-9930

· · · · · · · · · · · · · · · · · · ·	ATURES
* 2 in 1, 2000 A clamp meter + Digital multimeter.	* Wide ranges (2000A, 400 A) clamp on current
* Meet IEC 1010 CATIII 1000V safety requirement.	measurement both for ACA & DCA.
* True rms reading for ACV & ACA measurement.	* 4 ranges (400 uA, 4000 uA, 40 mA, 400 mA) direct
* 4000 counts, Auto range, multi-functions for ACA,	current input measurement both for ACA & DCA.
DCA, ACV, DCV, Ohms, Capacitance, Hz, Diode,	* Overload protection circuit is provided for all ranges.
Duty cycle and continuity check.	* Data hold, Relative key, Back light.
* LSI circuit provides high reliability and durability.	* Compact & heavy duty ABS and fireproof plastic case

	GENERAL SPE	CIFICATIONS	
Display	15 mm (0.6") LCD, 4 digits,	Operating Temp.	0 °C to 50 °C (32 °F to 122 °F).
COM	Max. indication 5000.	Operating	Less than 80% RH.
Measurement	ACA, DCA, ACV, DCV, Ohms, Diode, Hz,	Humidity	101 100 COM. 1
Range	Capacitance, Duty cycle, Continuity beeper.	Weight	380 g/0.85 LB (including battery).
Polarity	Automatic Switching, "-" indicates	Dimension	HWD: 255 x 73 x 38 mm.
	negative polarity.	TVI V	(10 x 2.9 x 1.5 inch)
Current Sensor	Hall effect sensor.	Max. Conductor	60 mm (2.36 inch) Dia.
Zero adjustment	DCA: Push bottom adjustment.	Size	1001. ON. 1
	Other ranges: Automatic adjustment.	Accessories	Operation manual 1 PC
Over-input	Indication of "1" or "-1".	Included	Test lead (red & black)
Sampling Time	Approx. 0.35 second.	WT	
Battery	DC 9V battery, heavy duty or Alkaline type,	Optional	Carrying case, Temperature Adapter,
	006P, MN1604 (PP3) or equivalent.	Accessories &	Light Adapter, Anemometer Adapter,
Power	Approx. DC 5 mA.	Adapters	Pressure Adapter, RH Adapter,
Consumption	LA TAN MAN TOOK	TIM	Tachometer Adapter, High Voltage Probe.

			FICATIONS (23 ± 5 $^{\circ}$ C)	
Function	Range	Resolution	Accuracy	Overload Protection
DC/AC	400 mV	0.1 mV	\pm (0.5 % + 2d)	WW. 100Y. CM.T
Voltage	(DC only)		N.T. COM.	MMM. COM
	4 V	0.001V	DCV:	AC/DC 1000 V.
	40 V	0.01V	± (1 % + 2d)	WW. 1007.
	400 V	0.1 V	ACV:	MMM. TO COM
	1000V	1 V	± (1.2 % + 5d)	W.100 COL
DC / AC Current	400 uA	0.1 uA	TWY TOOK OF THE	MAN 100X.Co
	4000 uA	1 uA	M. In COM.	AC/DC 500 mA (Fuse)
(Direct input)	40 mA	0.01 mA	± (1.2% + 5d)	
	400 mA	0.1 mA	WY.Co	TY WWW. 100X.C
DC /AC	400 A	0.1 A	± (2% + 5d)	N WWW.I
current	1007	.V.TW	W. 100x.	AC/DC
(Clamp on)	2000 A	1 A	± (2% + 8d)	2000A/1000V
Function	* ACA, ACV sp	quency response is from ecification be tested on Resolution	sine wave 50/60 Hz.	Overload Protection
	<i>Range</i> 400 ohm		Accuracy	Overioad Protection
Ohms	4 K ohm	0.1 ohm 1 ohm	MAN NOT	LOUIS WWW
	4 K Onm	10 ohm	± (1% + 5d)	AC / DC 400V
	400 K ohm	100 ohm	± (1 % + 5 d)	AC / DC 400V
	4 M ohm	1 K ohm	± (2% + 2d)	T.CO. TW
	40 M ohm	10Kohm	$\pm (3.5 \% + 5d)$	Z COM.
Capacitance	50 nF	10 pF	± (3.3 /0 + 3u)	TON TONI
	500 nF	100 pF	WW WW	AC / DC 400V
	5 uF	0.001 uF	± (3 % + 5d)	
	50 uF	0.00 r dr	* See Remark	7.07.20 1000
Frequency	5 Hz	0.001 Hz		
(> 5 V)	50 Hz	0.01 Hz	COM.	AC / DC 1000V
	500 Hz	0.1 Hz		
	5 KHz	1 Hz	± (1 % + 5 d)	
	50 KHz	0.01 KHz		
	500 KHz	0.1 KHz		
Duty cycle	1 % to	0.1 %		
	99 %			
Diode	Short/non cond	luctance, good/defect to	est	勝 特 力 材 料 886-3-
Continuity	If rmeasuring e	esistance is less than 10	ohm, the beeper will sound.	胜特力电子(上海) 86-21-

^{*} Appearance and specifications listed in this brochure are subject to change without notice.

勝 得 刀 材 科 886-3-5753170 胜特力电子(上海) 86-21-34970699 胜特力电子(深圳) 86-755-83298787

OOY.COM.T

Http://www.100y.com.tw