


### MCI-9101

SMB MALE CRIMP



RG/174/U RG/188/U RG/316/U




### MCI-9101S

SMB MALE CRIMP



RG/174/U RG/188/U RG/316/U




### MCI-9102

SMB FEMALE CRIMP



RG/174/U RG/188/U RG/316/U




### MCI-9102S

SMB FEMALE CRIMP



RG/174/U RG/188/U RG/316/U




### MCI-9104

SMB MALE RIGHT ANGLE CRIMP






RG/174/U RG/188/U RG/316/U



勝特力材料 886-3-5753170  
勝特力电子(上海) 86-21-54151736  
勝特力电子(深圳) 86-755-83298787  
[Http://www.100y.com.tw](http://www.100y.com.tw)




# MCI-9101S



勝特力材料 886-3-5753170  
 勝特力电子(上海) 86-21-34970699  
 勝特力电子(深圳) 86-755-83298787  
[Http://www.100y.com.tw](http://www.100y.com.tw)

勝特力材料 886-3-5753170  
 勝特力电子(上海) 86-21-34970699  
 勝特力电子(深圳) 86-755-83298787  
[Http://www.100y.com.tw](http://www.100y.com.tw)

# MCI-9102S



勝特力材料 886-3-5753170  
 勝特力电子(上海) 86-21-34970699  
 勝特力电子(深圳) 86-755-83298787  
[Http://www.100y.com.tw](http://www.100y.com.tw)

[www.100y.com.tw](http://www.100y.com.tw)