
Features

- 1. The fuse boxcar be mounted in TBR-N rail or panel directly.
- 2.Cabling range from 1.5m m²~8m m².
- 3. Make sure power has been cut off before change fuse. The indicator lamp will turn on when power is off.

Model Designation




Specifiction


Rated voltage Rated current	Operating temperature	Humidity	Application	Fuse size
600VAC max. 32A	-40 to 80°C	95%RH max.	Cable Protection Motor Protection	10×38

Dmensions














Description

TFBR-322N












TFBR-323N









Fuse box(With indicator lamp)

TFBR-321

TFBR-322

TFBR-323

勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-54151736 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw





