



Abmessungen:

Ampere	16	16	16	32	32	32
Pole	3	4	5	3	4	5
Flansch a	92	92	92	92	92	92
Flansch b	100	100	100	100	100	100
Lochabst. c	77	77	77	77	77	77
Lochabst. d	85	85	85	85	85	85
e	30	33	36	38	38	41
f	49	49	49	59	59	59
g	70	70	70	77	77	77
h	77	77	77	88	88	88
i	5,5	5,5	5,5	5,5	5,5	5,5
Gewicht in Gramm	121	141	175	195	219	247

勝特力材料 886-3-5753170
 勝特力电子(上海) 86-21-54151736
 勝特力电子(深圳) 86-755-83298787
[Http://www.100y.com.tw](http://www.100y.com.tw)

Bestellnummern:

Ampere	Pole	110V~ 50/60Hz 4h Best.Nr.	230V~ 50/60Hz 3p=6h 4p+5p=9h Best.Nr.	400V~ 50/60Hz 3p=9h 4p+5p=6h Best.Nr.	500V~ 50/60Hz 7h Best.Nr.	>50- 500V~ 100-300Hz 10h Best.Nr.	>50- 500V~ 301-500Hz 2h Best.Nr.
16	3	413-4f9	413-6f9	413-9f9	413-7f9	413-10f9	413-2f9
16	4	414-4f9	414-9f9	414-6f9	414-7f9	414-10f9	414-2f9
16	5	415-4f9	415-9f9	415-6f9	415-7f9	415-10f9	415-2f9
32	3	423-4f9	423-6f9	423-9f9	423-7f9	423-10f9	423-2f9
32	4	424-4f9	424-9f9	424-6f9	424-7f9	424-10f9	424-2f9
32	5	425-4f9	425-9f9	425-6f9	425-7f9	425-10f9	425-2f9