

## SX Series

### Silicon Pressure Sensors

0 psi to 1 psi to 0 psi to 150 psi

#### DESCRIPTION

The SX Series pressure sensors provide the lowest cost components for measuring pressures up to 150 psi. These sensors are designed for use with non-corrosive, non-ionic media, such as air and dry gases. Convenient pressure ranges are available to measure differential, gauge, and absolute pressures from 0 psi to 1 psi (SX01) up to 0 psi to 150 psi (SX150).

The Absolute (A) devices have an internal vacuum reference and an output voltage proportional to absolute pressure. The differential (D) devices allow application of pressure to either side of the diaphragm and can be used for gauge or differential pressure measurements.

This product is packaged in either the standard low cost chip carrier "button" package, a plastic ported "N" package, or a DIP package. All packages are designed for applications where the sensing element is integral to the OEM equipment. These packages can be o-ring sealed, epoxied, and/or clamped onto a pressure fitting. A closed-bridge four pin SIP configuration is provided for electrical connection to the "Button" or "N" Package. The DIP Package mounts on a PC board like a standard IC with through-hole pins. This extremely small size package enables the use of multiple sensors in applications with limited space.

#### FEATURES

- Low cost
- High-impedance bridge
- Absolute
- Differential (gage)
- Low noise
- Low power consumption for battery power

#### POTENTIAL APPLICATIONS

- Medical
- Instrumentation
- Barometric
- Measurement
- Pneumatic controls
- Battery powered equipment

# SX Series

## CHARACTERISTICS (Maximum ratings for all devices)

Supply voltage, V <sub>s</sub>	12 Vdc
Operating temperature range	-40 °C to 85 °C [-40 °F to 185 °F]
Storage temperature range	-55 °C to 125 °C [-67 °F to 257 °F]
Humidity	0 % to 100 % RH
Common-mode pressure	150 psig
Lead soldering temperature	250 °C [482 °F] 2 sec to 4 sec

## PERFORMANCE CHARACTERISTICS<sup>(1)</sup>

Characteristic description	Min.	Typ.	Max.	Unit
Zero pressure offset <sup>(2)</sup>	-35.0	-20.0	0.0	mV
Temperature coefficient of offset <sup>(3,4)</sup>	—	4	—	μV/V/°C
Combined pressure non-linearity, and hysteresis <sup>(5)</sup>	—	0.2	±0.5	%FSS
Long term stability of offset and span <sup>(6)</sup>	—	0.1	—	%FSS
Response time <sup>(7)</sup>	—	100	—	μs
Input resistance	—	4.1	—	kΩ
Temperature coefficient of resistance <sup>(3,4)</sup>	690	750	810	ppm/°C
Temperature coefficient of span <sup>(3,4)</sup>	-2550	-2150	-1900	ppm/°C
Output resistance	—	4.1	—	kΩ
Repeatability <sup>(8)</sup>	—	0.5	—	%FSS

## SX PERFORMANCE CHARACTERISTICS<sup>(1)</sup>

Part number	Operating pressure range	Sensitivity (mV/V/psi)	Full-scale span <sup>(9)</sup> (mV)			Burst pressure
		Typ	Min.	Typ.	Max. <sup>(10)</sup>	
SX01	0 psi to 1 psi	4.0	15	20	25	20 psi
SX05	0 psi to 5 psi	3.0	50	75	100	20 psi
SX15	0 psi to 15 psi	1.5	75	110	150	45 psi
SX30	0 psi to 30 psi	0.75	75	110	150	90 psi
SX100	0 psi to 100 psi	0.3	100	150	200	150 psi
SX150	0 psi to 150 psi	0.15	75	110	150	200 psi

### Specification Notes:

**Note 1:** Reference Conditions; TA = 25 °C [77 °F], Supply VS = 5 Vdc; Common Line Pressure = 0 psig, Pressure Applied to P1

**Note 2:** The zero pressure offset is 0 mV minimum to -20 mV typical and 35 mV maximum for part numbers SXxxxGD2 and SXxxxDD4.

**Note 3:** Slope of best straight line fit from 0°C to 70°C. For operation outside this temperature range, contact factory for more information.

**Note 4:** This parameter is not 100% tested. It is guaranteed by process design.

**Note 5:** Pressure Hysteresis - the maximum output difference at any point within the operating pressure range for increasing and decreasing pressure.

Pressure Non-linearity the maximum deviation of measure output, at constant temperature (25 °C [77 °F]), from "best straight line" through three points (offset pressure, full-scale pressure, one-half full scale pressure).

**Note 6:** Long term stability over a one year period.

**Note 7:** Response time for a 0 psi to Full-Scale Span pressure step change, 10% to 90% rise time.

**Note 8:** Maximum difference in output at any pressure within the operating pressure range and the temperature range within 0 °C to 70 °C [32 °F to 158 °F] after:

a) 100 temperature cycles, 0 °C and 70 °C [32 °F to 158 °F]


b) 1 million pressure cycles, 0 psi to full-scale span.

**Note 9:** Full-scale span is the algebraic difference between the output voltage at full-scale pressure and the output at zero pressure. Full-scale span is ratiometric to the supply voltage.


**Note 10:** Exceeding maximum pressure can cause permanent sensor failure

# Silicon Pressure Sensors, 0 psi to 1 psi to 0 psi to 150 psi


## EQUIVALENT CIRCUITS



Button, Nipple and N Packages

DIP Packages  
(Absolute Version Only)

## ELECTRICAL CONNECTIONS




## ORDERING INFORMATION

Pressure Range	Order Part Number			
	Button Package	Nipple Package	"N" Package	DIP Package
0 to 1 psid or psig	SX01D	SX01DP1	SX01DN	SX01GD2, SX01DD4
0 to 5 psid or psig	SX05D	SX05DP1	SX05DN	SX05GD2, SX05DD4
0 psia to 15 psia	SX15A	SX15AP1	SX15AN	SX15AD2, SX15AD4
0 psia to 30 psia	SX30A	SX30AP1	SX30AN	SX30AD2, SX30AD4
0 psia to 100 psia	SX100A	—	SX100AN	SX100AD2, SX100AD4
0 psia to 150 psia	SX150A	—	SX150AN	—
0 to 15 psid or psig	SX15D	SX25DP1	SX15DN	SX15GD2, SX15DD4
0 to 30 psid or psig	SX30D	SX30DP1	SX30DN	SX30GD2, SX30DD4
0 to 100 psid or psig	SX100D	—	SX100DN	SX100GD2, SX100DD4
0 to 150 psid or psig	SX150D	—	—	—


# SX Series

PHYSICAL DIMENSIONS for reference only mm [in]


## Button package



## Nipple package




## N Housing package




# Silicon Pressure Sensors, 0 psi to 1 psi to 0 psi to 150 psi


## D2 DIP package



## DD4 DIP package



## AD4 DIP package



## **WARNING**

### **PERSONAL INJURY**

DO NOT USE these products as safety or emergency stop devices or in any other application where failure of the product could result in personal injury.

**Failure to comply with these instructions could result in death or serious injury.**

### **WARRANTY/REMEDY**

Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship. Honeywell's standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgement or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge those items it finds defective. **The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential, special, or indirect damages.**

While we provide application assistance personally, through our literature and the Honeywell web site, it is up to the customer to determine the suitability of the product in the application.

Specifications may change without notice. The information we supply is believed to be accurate and reliable as of this printing. However, we assume no responsibility for its use.

勝特力材料 886-3-5753170  
勝特力电子(上海) 86-21-34970699  
勝特力电子(深圳) 86-755-83298787  
[Http://www.100y.com.tw](http://www.100y.com.tw)

## **WARNING**

### **MISUSE OF DOCUMENTATION**

- The information presented in this product sheet is for reference only. Do not use this document as a product installation guide.
- Complete installation, operation, and maintenance information is provided in the instructions supplied with each product.

**Failure to comply with these instructions could result in death or serious injury.**

### **SALES AND SERVICE**

Honeywell serves its customers through a worldwide network of sales offices, representatives and distributors. For application assistance, current specifications, pricing or name of the nearest Authorized Distributor, contact your local sales office or:

**E-mail:** [info.sc@honeywell.com](mailto:info.sc@honeywell.com)

**Internet:** [www.honeywell.com/sensing](http://www.honeywell.com/sensing)

#### **Phone and Fax:**

Asia Pacific +65 6355-2828

+65 6445-3033 Fax

Europe +44 (0) 1698 481481

+44 (0) 1698 481676 Fax

Latin America +1-305-805-8188

+1-305-883-8257 Fax

USA/Canada +1-800-537-6945

+1-815-235-6847

+1-815-235-6545 Fax

Sensing and Control

**Honeywell**

1985 Douglas Drive North

Golden Valley, MN 55422

[www.honeywell.com](http://www.honeywell.com)

# Honeywell

008136-2-EN IL50 GLO Printed in USA  
April 2009  
© 2009 Honeywell International Inc.