POCKET HUMIDITY METER

Model: HT-315 *ISO-9001, CE, IEC1010*



Features:

- * *Measurement :*Humidity, Temperature, Dew point
- * Resolution:
 0.01 %RH, 0.01 degree.
- * Fast response time.
- * Separate probe.
- * Pocket and compact housing case.
- * Max., Min. measurement.
- * Data hold.
- * LCD display.
- * DC 006P 9 V battery.
- * Size: 135 x 60 x 33 mm.

勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-34970699 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw





The Art of Measurement

Humidity + Temp. + Dew Point, Seperate probe

HUMIDITY METER

Model: HT-315

1. FEATURES

* Humidity + Temperature + Dew point are combined				
into one meter, intelligent and professional.				
* 0.01 %RH resolution for the humidity reading,				
0.01 degree resolution for the Temp. reading.				
* Pocket size with Separate humidity & temp. probe,				
easy operation. & remote measurement.				
* Fast humidity measuring response time.				
* High accuracy and high precision.				
* Dew point measurement.				
* Manual and auto manual data logger.				
* Just few panel buttons, easy operation.				
* Microprocessor circuit assures maximum possible				
accuracy, provides special functions and features.				
* LCD with two display, easy readout.				
* Heavy duty & compact housing case, designed				
for easy carry out & operation.				
* Records Maximum and Minimum readings with Recall.				
* Auto shut off saves battery life.				
* Data hold function for freezing the desired value				
on display.				
* RS 232 PC serial interface.				
* Show the humidity & temperature values on the				
LCD display at same time.				
* Built-in low battery indicator.				
Wide humidity & temp. measuring range.				
* DC 9V power adapter input socket.				

2-1 General Specifications

Circuit	Custom one-chip of microprocessor LSI circuit.		
Display	LCD size: 44 mm x 29 mm		
	dual function LCD display.		
Measurement	Humidity: %RH (Relative Humidity)		
Unit	Temperature : °C or °F.		
	Dew point : °C or °F.		
Response Time	5 to 30 seconds typically.		
	@ Reach the 85% reading value		
Temperature	Automatic temp. compensation for the		
Compensation	humidity function.		
Data Hold	Freeze the display reading.		
Memory Recall	Maximum & Minimum value.		
Sampling Time	Approx. 0.8 second.		
Power off	Auto shut off saves battery life or manual		
	off by push button.		

Data Output	RS 232 PC serial interface.			
Operating	Meter 0 to 50 °C.			
Temperature	Probe 0 to 80 °C.			
Operating	Main instrument: Less than 85% R.H.			
Humidity	Probe: 0 to 95 %RH.			
Power Supply	006P DC 9V battery			
TW	(Alkaline or Heavy duty type).			
Power Current	Approx. DC 4.6 mA.			
Weight	264 g/0.67 LB.			
Dimension	Main instrument :			
COM.TW	135 x 60 x 33 mm,			
	(5.3 x 2.4 x 1.3 inch).			
	Humidity Sensor Probe :			
CONTY	197 mm (7.8 inch) in length.			
Accessories	Instruction manual1 PC			
Included	Humidity and Temp. probe1 PC			
Optional	RS232 cable, UPCB-02			
Accessories	USB cable, USB-01			
	Data Acquisition software, SW-801-WIN			
	Case wall holder			
N. T. CO	Power adapter (ACV to DC 9V)			

2-2 Electrical Specifications (23±5 °C)

Humidity/ Temperature				
	Range	10 % to 95 % R.H.		
Humidity	Resolution	0.01 % R.H.		
MMM.TO	Accuracy	≧70% RH :		
	COM.	± (3% reading + 1% RH).		
WWW.1	OULCON	< 70% RH :		
	1001	± 3% RH.		
	Range	0 ℃ to 80 ℃,32 ℉ to 176 ℉.		
Temperature	Resolution	0.01 degree		
* Probe	Accuracy	℃ - 0.8 ℃.		
	W.Ivo	°F - 1.5 °F.		

Dew Point	1001	COMITY
$^{\circ}\mathbb{C}$	Range	-25.3 °C to 48.9 °C
W	Resolution	0.01 ℃
°F	Range	-13.5 °F to 120.1 °F.
1.1	Resolution	0.01 °F.

Remark :

- * Dew Point display value is calculated from the Humidity/Temp. measurement automatically.
- * The Dew Point accuracy is sum accuracy value of Humidity & Temperature measurement..

^{*} Appearance and specifications listed in this brochure are subject to change without notice.