USER'S GUIDE HS-3(V) HS-6

100Y.COM.

CASIO.


WY.COM.TW

WWW.100Y.COM

WWW.100

1





· A sticker is affixed to the glass of this stopwatch when you purchase it. Be sure to remove the sticker before using the stopwatch.

Depending on the stopwatch model, the configuration of your stopwatch may differ somewhat from that shown in WWW.100Y.COM.TW the illustration.

WW.100Y.COM.

WWW.1001

WWW.100Y.COM.

力材料 886-3-5753170 特 勝 胜特力电子(上海) 86-21-54151736 胜特力电子(深圳) 86-755-83298787 Http://www. 100y. com. tw

WWW.100Y.COM.

WWW.100Y.COM

USER'S GUIDE HS-3(V) HS-6

CASIO

USING THE STOPWATCH

- (A) Press this button to start and stop elapsed time measurement.
- (B) Press this button while an elapsed time measurement is in progress to momentarily freeze a SPLIT or LAP time on the display (timing continues internally). Press again to display the ongoing time measurement. You can repeat the LAP/SPLIT time operation as many times you want. Pressing this button while elapsed time measurement is stopped resets the time to all zeros.
- © Press this button to toggle between the SPLIT time mode and LAP time mode.

• The maximum elapsed time that can be measured is 9 hours, 59 minutes, 59.99 seconds.

e the stopwatch asurement			
	STOP		
a	(a)		
WW.I	Press (A).		
mulated time excludi	ng loss time)	10 2010.	
STOP	START	STOP	
(a)	(a) t) (a+b)	
	asurement a mulated time excludi STOP	asurement a STOP (a) Press (A). mulated time excluding loss time) STOP START	asurement a STOP a (a) Press (A). Press (B) to to zero. mulated time excluding loss time) STOP START STOP

SPLIT timing START STOP 0 (a) h (a+b) С (a+b+c) (t) a ----> SPLIT (a) Press (A). SPLIT (a+b) SPLIT (a+b+c) Press (B) Press (A) in Press (B) to freeze SPLIT Press (B) to freeze SPLIT to reset. SPLIT mode. time (a). Press (B) to release. time (a+b). Press (B) to release. 1st-2nd place times START SPLIT STOP RESET SPLIT release (a) 0 (b) b (a) (b) Press (B) when the Press (A) when the Press (B) to Press (B) Press (A) in SPLIT second runner (b) display the time of first runner (a) to reset. mode. finishes. finishes. the second runner. Displays time of first runner. · LAP timing (Lap timing for each segment of an event) START STOP STOP STOP START START 0 b (C) а (a) (b) С LAP (a) LAP (b) LAP (c) Press (A) in Press (B) to Press (B) to Press (A). freeze LAP freeze LAP LAP mode. Press (B) to reset time (a). time (b). Press (B) to Press (B) to release. release.

勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-54151736 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw

2

WWW.100Y.COM