


勝 特 力 材 料 886-3-5753170 胜特力电子(上海) 86-21-54151736 胜特力电子(深圳) 86-755-83298787 Http://www.100y.com.tw



Weight: 1.44 g

Suitable Cables: RG174, RG188, RG316, JBY100, RG316-E, RG316-FEP

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION MCX8100-0316 JYE BAO CO., LTD. **FERRULE CONTACT PIN BODY** ASSEMBLY INSTRUCTION DIAGRAM Step 1: STRIP AS SHOWN. 4.6 4.0 [.181] 2.5 [.098] Step 2: SLIDE FERRULE "A" OVER CABLE. Step 3: PUT PIN "B" ON CENTER CONDUCTOR AND CRIMP IN "Y". Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR "C" IN PLACE. Step 5: SLIDE FERRULE "A" TOWARDS THE CONNECTOR "C" AND CRIMP. WWW.100Y.COM.TW

Notice: JYEBAO reserves the right to make modifications deemed appropriate.